




heat sinks

= 12 =
WT: (KG/M)
R_e: (°C/W/1")

K102

WT: 5.07


R_e: 2.3



K127

WT: 3.86


R_e: 2.0



K133

WT: 3.31


R_e: 2.6



K128

WT: 4.3


R_e: 1.9



K156

WT: 2.29


R_e: 5.9



K548

WT: 7.3


R_e: 1.5



K162

WT: 2.91


R_e: 4.4



K197

WT: 5.28


R_e: 4.9



K198

WT: 14.95

R_e: 1.4



K195

WT: 6.03

R_e: 4.5

