




heat sinks

= 11 =
WT: (KG/M)
R_a: (°C/W/1")

K155

WT: 9.44


R_a: 2.7



K164

WT: 15.74


R_a: 1.7



K153

WT: 12.05


R_a: 2.1



K158

WT: 13.5


R_a: 1.9



K129

WT: 8.07

R_a: 1.1



K180

WT: 15.8

R_a: 1.0

